

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/06/2023

Submitted Date:

11/06/2023

Document Number:

690011656

FIELD INSPECTION FORM
 Loc ID 410026 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292274	WELL	PR	07/01/2022	GW	123-26281	MCGLOTHLIN 22-6X	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.253420,-104.820490	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:	Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	292274	Type:	WELL	API Number:	123-26281	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/28/2023		Annual Brhd Completed?						
Last Brhd Test Results	Initial Surf Csg Pressure:	1	Fluid Type:	None					
	End Surf Csg Pressure:	--							
Comment:	Plumbed to surface.								
Corrective Action:				Date:					