

Inspection Photos
Location Name: Foose USX/A18-23
Location #: 420665



Photo #1

Foose A18-23 (123-32666) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Surface plug



Photo #2

Foose A18-23 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Surface plug
Site safety signage



Inspection Photos
Location Name: Foose USX/A18-23
Location #: 420665



Photo #3
Foose A18-23 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Surface plug
Wellsite entrance
prior photo




Photo #4
Foose A18-23 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Surface plug
JSA: 2023-11-06



Inspection Photos

Location Name: Foose USX/A18-23

Location #: 420665



Photo 5

Foose A18-23 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: Surface plug

Battery sign

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources