

Final Reclamation Inspection

November 1st, 2023

Operator: Logos Operating LLC - 10679

Location ID: 325146

Inspection Document #: 714000113

La Plata County, CO

Township: SWNW 14 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 1
Location ID: 325146



Photo 1. View of the project area taken from the northern edge facing center.

Inspection Photos
Location Name: Bondad 33-9 1
Location ID: 325146



Photo 2. Cardinal photos taken from the middle of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Bondad 33-9 1
Location ID: 325146



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: project area appears consistent with adjacent reference area, see photo 4.

Inspection Photos
Location Name: Bondad 33-9 1
Location ID: 325146



11/1/23
+37.106012,-107.801473
209° SW

Photo 4. Reference area comprised of juniper, sagebrush, crested wheatgrass and indian rice grass.