

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		
Comment:	Shares containment with crude oil				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.291048,104.711527
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-29682
123-35722
123-29227

AirsID

API Number	AirsID
------------	--------

123-35123

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 300342 Type: WELL API Number: 123-29682 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 427833 Type: WELL API Number: 123-35122 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 427839 Type: WELL API Number: 123-35123 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On (11-7-23) at approximately (10:45 HRS), I, Inspector (Abe Serna), Conducted an on-site inspection at (Tulo G 30-28) (Noble Energy), at (Location #300342) in (Weld County) Colorado. While there, I observed a (TA Well) During this inspection no compliance issues were observed No follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p>	sernaa	11/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698705367	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313523