

# Inspection Photos

Location Name: CAERUS PICEANCE LLC JEWELL 22-10 (022) Pad

Location #: 335460



Photo # 5432 From entrance to location



Photo # 5433 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC JEWELL 22-10 (022) Pad

Location #: 335460



Photo # 5434 Location



Photo # 5435 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC JEWELL 22-10 (022) Pad

Location #: 335460



Photo # 5436 Location



Photo # 5437 Location

Inspection Photos  
Location Name: CAERUS PICEANCE LLC JEWELL 22-10 (022) Pad  
Location #: 335460




Photo # 5438 Tank label damaged & illegible

Photo # 5439 Tank label damaged & illegible

## Inspection Photos

Location Name: CAERUS PICEANCE LLC JEWELL 22-10 (022) Pad

Location #: 335460



Photo # 5440



Photo # 5441 Open ended load line

## Inspection Photos

Location Name: CAERUS PICEANCE LLC JEWELL 22-10 (022) Pad

Location #: 335460



Photo # 5442 Debris