

Inspection Photos 11/7/23
Location Name: Marie Gerhardt B 4
API: 05-123-08603



Well access



**Plunger lift has been removed
and converted to polished rod**



**Lease sign laying on the ground
needs to be installed to comply
with Rule 605.d.**