

Final Reclamation Inspection

October 30, 2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319208

Inspection Document #: 697504941

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HART-64N68W 15NESE
Location ID: 319208




Photo 1. Photo taken from the off location tank battery, facing West. Photo illustrates the meter house remains on location.



Photo 2. Photo taken from the off location tank battery, facing South. See comments under Photo 1.



Photo 3. Google Earth aerial imagery taken on 4/29/2023 illustrates the well location, flowline disturbance and off location tank battery.