

# Inspection Photos

11/06/2023

**Operator:** NONSUCH NATURAL GAS INC

#10163

**Location ID:** 324169

**Inspection Doc:** 696205408

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 1:** Photos 1-2 taken from the west end of the working pad surface. Photos provide an overview of the Location from north, northeast, southeast to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 3:** Photos show the two methanol tanks on Location. Photo left show BMPs (netting) to mitigate wildlife access to the containment BMP has been installed. Photo right shows BMP (netting) remains in disrepair.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



November 6, 2023

**Photo 4:** Photo shows perimeter fence at the pit remains in disrepair.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 5:** Photos show netting (arrow) has not been replaced over the pit.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 6:** Photo shows what appears to be a patch observed floating within the pit; patch appears to have detached from the liner at some unknown point.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



November 6, 2023



November 6, 2023

**Photo 7:** Photos taken from the interim areas on the east end of the Location. Unable to find evidence that reclamation has been performed per CAs and 1003 rules. Photos also examples showing control measures to manage runoff, and to minimize erosion, degradation and sediment transport remains missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 8:** Photos taken from the interim areas on the east end of the Location. Unable to find evidence that reclamation has been performed per CAs and 1003 rules. Photos also examples showing control measures to manage runoff, and to minimize erosion, degradation and sediment transport remains missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 9:** Photos taken from the interim areas on the west end of the Location. Unable to find evidence that reclamation has been performed per CAs and 1003 rules. Photos also examples showing control measures to manage runoff, and to minimize erosion, degradation and sediment transport remains missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 10:** Photos example showing Noxious Weeds (hounds tongue, common mullein) observed on the Location. Weeds observed had reached maturity.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



**Photo 11:** Photos taken from the access road. Stormwater and erosion control measures to manage runoff at road remain missing or insufficient, resulting in persisting off-site sediment transport and degradation (photo right).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources