

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7SWSE

Location ID: 334691

Date: 11/7/2023



Location Entrance – Photo #07368



Location Entrance – Photo #07369

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7SWSE

Location ID: 334691

Date: 11/7/2023



Wellheads – Photo #07370



Separators – Photo #07371

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7SWSE

Location ID: 334691

Date: 11/7/2023



Tank Battery – Photo #07373