

Inspection Photos
Location: Bud 34-6
Facility ID: 307358



Photo 1 –Well Site Placard

Photo 2 – Launcher/Receiver for Gas Gathering line

Inspection Photos
Location: Bud 34-6
Facility ID: 307358



Photo 3 – Engine Shed

Photo 4 – Wellhead and Engine shed

Inspection Photos

Location: Bud 34-6

Facility ID: 307358



Photo 5 – Pit Facility ID 257819

Photo 6 – Access road looking west with Erosion



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location: Bud 34-6
Facility ID: 307358



Photo 7 – Main Access, Vehicle Rutting