

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TONDER 17-1 (PA17) Pad

Location ID: 334758



Photo # 5542 From entrance to location



Photo # 5543 From entrance to location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC TONDER 17-1 (PA17) Pad

Location ID: 334758




Photo # 5544 Location



Photo # 5545 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC TONDER 17-1 (PA17) Pad

Location ID: 334758



Photo # 5546 Location



Photo # 5547 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TONDER 17-1 (PA17) Pad

Location ID: 334758



Nov 6, 2023 at 11:55:38 AM  
CO



Nov 6, 2023 at 11:54:31 AM  
CO

Photo # 5548 Location

Photo # 5549 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TONDER 17-1 (PA17) Pad

Location ID: 334758



Photo # 5550 Hole in liner/liner needs maintenance



Photo # 5551 Hole in liner/liner needs maintenance

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TONDER 17-1 (PA17) Pad

Location ID: 334758



Photo # 5552 Hole in liner/liner needs maintenance



Photo # 5553 Hole in liner/liner needs maintenance