

Final Reclamation and Stormwater Inspection

Date: 10/24/23

Operator: Bonanza Creek Energy Operating
Company LLC. - 8960

Location ID: 306037

Inspection Document #: 713900049

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn 31-9
Location ID: 306037



Photo 1. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the location information sign.

Photo 2. The photo was taken at the entrance to the well location facing Southeast. The photo illustrates the location access road.

Inspection Photos
Location Name: Pronghorn 31-9
Location ID: 306037



Photo 3. The photo was taken at the well location facing East. The photo illustrates the location is dominated by cereal rye and russian thistle. The photo also illustrates the cut is still apparent on the location.



Photo 4. The photo was taken at the well location facing South. The photo illustrates the well location is dominated by russian thistle and cereal rye.

Inspection Photos
Location Name: Pronghorn 31-9
Location ID: 306037



Photo 5. The photo was taken at the well location facing Northeast. The photo illustrates large patches of bare soil on location.

Photo 6. The photo was taken at the well location facing East. The photo illustrates gravel left on location.

Inspection Photos
Location Name: Pronghorn 31-9
Location ID: 306037



Photo 7. The reference photo was taken South of the well location facing Southwest.