

**Inspection Photos**  
**Location Name: Anschutz-Williams 5-61-27 SWSW PAD**  
**Location ID: 452726**



**Photo 1 – Sign at Entrance**



**Photo 2 – Wellheads**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



**Photo 3 – VRTs and Separators**



**Photo 4 – South Separator – Open**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



**Photo 5 – South Separator – Open**



**Photo 6 – Gas Meters – Tumbleweed Debris**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



**Photo 7 – Compressors – Tumbleweeds**



**Photo 8 – Line Heater – Tumbleweed Debris**





## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



**Photo 9 – VRUs**



**Photo 10 – Locate Flags – no longer valid or in use**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



**Photo 11 – Condensate Vault – Buried by Sand – Labels no longer visible**




**Photo 12 – Production Equipment**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



Energy and Carbon Management Commission  
40.36567, -104.20354, 4552.4ft  
11/02/2023 13:43:28

**Photo 13 – Tumbleweeds Debris inside Tank Berm**



Energy and Carbon Management Commission  
40.36566, -104.20372, 4542.0ft  
11/02/2023 13:44:09

**Photo 14 – Capacity Label missing – NW Corner on Tank Berm**



# Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD  
Location ID: 452726



Photo 15 – LACT



Photo 16 – Tank Battery Signs



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



Energy and Carbon Management Commission  
40.36553, -104.20357, 4548.8ft  
11/02/2023 13:45:12

**Photo 17 – LACT – Tumbleweed Debris**



Energy and Carbon Management Commission  
40.36552, -104.20337, 4539.9ft  
11/02/2023 13:45:55

**Photo 18 – ECDs**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW PAD

Location ID: 452726



**Photo 19 – Tank Battery**

