

Interim Reclamation and Stormwater Inspection

Date: 11/02/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 323023

Inspection Document #: 708200677

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bashor-69N60W 18SWNW
Location ID: 323023



Photo 1. Areas west of the well do not appear to be progressing towards Rule 1003 standards and are not reflective of adjacent reference areas. Undesirable vegetation (e.g. russian thistle and kochia) and areas of bare/exposed soils evident.

Inspection Photos
Location Name: Bashor-69N60W 18SWNW
Location ID: 323023



Photo 2. Continued from Photo 1.

Inspection Photos
Location Name: Bashor-69N60W 18SWNW
Location ID: 323023



Photo 3. North of wellhead; see comments in Photo 1.

Inspection Photos
Location Name: Bashor-69N60W 18SWNW
Location ID: 323023



Photo 4. Northwest of tank battery; see comments in Photo 1.

Inspection Photos
Location Name: Bashor-69N60W 18SWNW
Location ID: 323023



Photo 5. East of tank battery; see comments in Photo 1.

Inspection Photos
Location Name: Bashor-69N60W 18SWNW
Location ID: 323023



Photos 6 & 7. Debris (rubber and plastic, tumbleweed debris) on location next to tank battery.