

Interim Reclamation and Stormwater Inspection

Date: 11/02/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 431925

Inspection Document #: 708200682

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Nelson 2-17-9-60 Pad
Location ID: 431925



Photo 1. Interim areas are not progressing towards Rule 1003 standards as they are not reflective of adjacent reference areas. Evidence of undesirable vegetation (e.g. kochia and russian thistle) was observed throughout the interim areas; the areas have been recently mowed.

Inspection Photos
Location Name: Nelson 2-17-9-60 Pad
Location ID: 431925



Photos 2 & 3. Taken from the southeast corner of the location. See comments in Photo 1.

Inspection Photos

Location Name: Nelson 2-17-9-60 Pad

Location ID: 431925



Photos 4 & 5. Taken from the northern/topsoil portion of the location. The topsoil is not properly stabilized with evidence of non-uniform vegetative cover resulting in bare/exposed soil. Additionally, the predominant vegetative cover is undesirable vegetation (e.g. russian thistle and kochia).

Inspection Photos
Location Name: Nelson 2-17-9-60 Pad
Location ID: 431925



Photo 6. Taken from the northwestern corner of the location. See comments in Photo 1.