

Operator: CRESTONE PEAK RESOURCES
Location Name: ARISTOCRAT ANGUS-63N65W 10SENE
Loc ID: 332743
Inspection: 709400560



Exhibit A



Exhibit B



Exhibit C

CA: Fencing at entrance of location is down. See inspection photos. Comply with Rule 606 The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

CA Resolution: Fence has been repaired to comply with Rule 606.