

WELL SITE INSPECTION FORM



00524215

WELL NAME LAKE ALBERT #1-2 API NUMBER 05 - 061 - 06501
OPERATOR MEDALLION PETR PERMIT NUMBER 88 - 252
LOCATION NWSW 2 17S 43W COUNTY KIOWA
FIELD WILDCAT INSPECTOR SHELTON

AL/PA/DA INSPECTION RESULTS: WELL STATUS:
PASS(Y) Y FAIL(N) DATE 10/20/88 FN FD WO

DATE OF INSPECTION BEFORE/DURING DRILLING

CASING SIZE DEPTH SET CMT VOL WOC
CONSISTENT WITH APD CASING PROGRAM? RETURNS
RIG BOP'S CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION

PIPE SET? COMPLETION RIG/ACTIVITY
DRILLING PITS: CLOSED OPEN WELLHEAD SYSTEM INSTALLED
TANK ID: YES NO NA WELL SIGN: YES NO
SKIM PIT: gal TANKS: () bbls
EQUIPMENT
BRADENHEAD PRESSURE FLUID: NO YES TYPE
METER RUN: YES NO WELL STATUS: PR TA SI WELL CAT 3-

AL/PA/DA INSPECTION

DATE PLUGGED: 4/30/88 DATE PERMIT EXPIRED:
HOLE PLUGGED: YES X NO PITS BACKFILLED: YES X NO
MATERIAL BURIED: YES NO NA X SITE CLEAN: YES X NO
BOND RELEASE OK: YES X NO FED HOLE MARKER: YES NO X

DATE OF SAFETY/STATUS INSPECTION 10/20/88

COMMENTS SITE RESTORED - CLEAN, LEVEL, DRY IN PLOWED FIELD