





TANK BATTERY DECOMMISSIONING FORM

SITE NAME: Bryant 9&34-30A O SA							DATE: 11/8/2023	REM. PROJECT #:		WEATHER: 40s cloudy	
SITE DIRECTIONS: CR CR 3 1/4, 16 1/2, E 1 mile, S in							CLIENT: Oxy				
LEGALS AND LAT/LONG: (40.1060247, -105.0396693)							TASMAN PERSONNEL: A Tran, P Downs, K Magourik				
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: South				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
11/8/2023 11:58	AST-B01@3"	0.1	No Staining	No Odor	Yes	N/A	Buried or Partially Buried Vessel				
11/8/2023 12:00	AST-B02@3"	3.3	No Staining	No Odor	Yes	Lab	Separator				
11/8/2023 12:02	PWV-B01@5'	0.1	No Staining	No Odor	Yes	Lab	Emission Control Device (ECD)				
11/8/2023 12:04	PWV-N01@2'	0.1	No Staining	No Odor	Yes	N/A	Dump Line				
11/8/2023 12:08	PWV-S01@2'	0.1	No Staining	No Odor	Yes	N/A	Wellhead				
11/8/2023 12:06	PWV-E01@2'	0.1	No Staining	No Odor	Yes	Lab	Flowline				
11/8/2023 12:10	PWV-W01@2'	0.1	No Staining	No Odor	Yes	N/A	Other:				
11/8/2023 12:12	MH-B01@3"	0.1	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
11/8/2023 12:14	ECD-B01@3"	0.0	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
11/8/2023 12:24	SEP3-B01@4'	0.3	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
11/8/2023 12:16	SEP3-B02@4'	20.1	No Staining	No Odor	Yes	Lab	Date		Number	CY	
11/8/2023 12:18	SEP4-B01@4'	0.1	No Staining	No Odor	Yes	Lab					
11/8/2023 12:20	SEP4-B02@4'	0.5	No Staining	No Odor	Yes	Lab					
11/8/2023 12:22	SEP5-B01@4'	0.0	No Staining	No Odor	Yes	Lab					
11/8/2023 12:24	SEP5-B02@4'	0.7	No Staining	No Odor	Yes	Lab					
							Total Removed		0	0	
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED:		DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				



Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

											
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:					
Material:		Volume:		Contents:		Material:		Volume:		Contents:	
Notes/Conditions:						Notes/Conditions:					

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			