

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-3 (C8E) Pad

Location ID: 334799



Photo # 5695 From entrance to location




Photo # 5696 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY 8-3 (C8E) Pad
Location ID: 334799



Photo # 5697 Location



Photo # 5698 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-3 (C8E) Pad

Location ID: 334799



Photo # 5699 Location



Photo # 5700 COUEY 8-3 bradenhead line connected to flow line.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-3 (C8E) Pad

Location ID: 334799



Photo # 5701 COUEY 8-3 bradenhead line connected to flow line.



Photo # 5702 COUEY 8-3 bradenhead line connected to flow line.