

Inspection Photos

Operator: SCOUT ENERGY MANAGEMENT LLC - 10779

Location Name: MCLAUGHLIN, A.C. #94X


Location ID: 316527 API #: 05-103-10725

Inspection Date: 11/9/2023 Inspection Doc#: 693806533



11.09.2023 12:14

Injection well during MIT



11.09.2023 12:36

Form 21 field copy