

Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location ID: 324233

Date: 11/8/2023



Location Entrance – Photo #07383



Wellhead – Photo #07384

Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location ID: 324233

Date: 11/8/2023



Separator – Photo #07386



Tank Battery – Photo #07385



Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY-66S99W/20NESE

Location ID: 324233

Date: 11/8/2023



Unprotected Soil Stockpile – Photo #07388



Unprotected Soil Stockpile – Photo #07389