

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



Location Overview: Location is within Black Bear/High Priority/Density Habitat areas & within close proximity to NSO Habitat area. Location is approximately 424 yards from Porcupine Creek.

Section/Township/Range: 2 7S94W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



Photo # 6210 Erosion & transport of sediment off location



Photo # 6211 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



Photo # 6212 Erosion & transport of sediment off location



Photo # 6213 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



Photo # 6214 Erosion & transport of sediment off location



Photo # 6215 Erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



Photo # 6216 Erosion & transport of sediment off location



Photo # 6217 Erosion & transport of sediment off location