

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7SENW

Location ID: 334728

Date: 11/9/2023



Nov 9, 2023 at 13:03:34
Parachute CO 81635
United States



Nov 9, 2023 at 13:04:24
Parachute CO 81635
United States

Location Entrance – Photo #07453

Wellheads – Photo #07457

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/7SEW

Location ID: 334728

Date: 11/9/2023



Separators – Photo #07456



Tank Battery – Photo #07455