

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/13/2023

Submitted Date:

11/13/2023

Document Number:

714200298

**FIELD INSPECTION FORM**

Loc ID 318488 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| ,            |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 434049      | WELL | PR     | 05/11/2015  | OW         | 123-37913 | GREENLEAF 15N-15HZ  | SI          |
| 434053      | WELL | PR     | 04/04/2015  | OW         | 123-37916 | GREENLEAF 36N-15HZ  | SI          |
| 434063      | WELL | PR     | 09/01/2023  | OW         | 123-37922 | GREENLEAF 37C-15HZ  | SI          |
| 434085      | WELL | PR     | 05/11/2015  | OW         | 123-37937 | GREENLEAF 16N-15HZX | SI          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Type               | TANK BATTERY |       |  |
| Comment:           | iron         |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | iron         |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | iron         |       |  |
| Corrective Action: |              | Date: |  |

**Equipment:**

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| Type: Gas Meter Run               | # 1 |       | corrective date |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 7 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bradenhead                  | # 4 |       |                 |

|                               |     |  |       |
|-------------------------------|-----|--|-------|
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Bird Protectors         | # 9 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Plunger Lift            | # 4 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Emission Control Device | # 2 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Vertical Separator      | # 1 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Horizontal Separator    | # 1 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | PBV FIBERGLASS |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 210 BBLs |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares containment with other tanks. |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |

|                    |  |
|--------------------|--|
| Other (Type) _____ |  |
|--------------------|--|

**Berms**

| Type                     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------------|----------|---------------------|---------------------|-------------|
| Metal                    | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment: _____           |          |                     |                     |             |
| Corrective Action: _____ |          |                     |                     | Date: _____ |

**Venting:**

|                          |    |  |             |
|--------------------------|----|--|-------------|
| Yes/No                   | NO |  |             |
| Comment: _____           |    |  |             |
| Corrective Action: _____ |    |  | Date: _____ |

**Flaring:**

|                          |  |             |
|--------------------------|--|-------------|
| Type                     |  |             |
| Comment: _____           |  |             |
| Corrective Action: _____ |  | Date: _____ |

**Inspected Facilities**

Facility ID: 434049 Type: WELL API Number: 123-37913 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

Facility ID: 434053 Type: WELL API Number: 123-37916 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

Facility ID: 434063 Type: WELL API Number: 123-37922 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

Facility ID: 434085 Type: WELL API Number: 123-37937 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| no corretive actions were observed at the time of inspection .<br>**Weather Conditions: sunny, dry ground. | santistb | 11/13/2023 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 714200299    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6319968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6319968</a> |