

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 11/13/2023



Location Entrance – Photo #07487



Wellheads – Photo #07488

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SESE

Location ID: 334876

Date: 11/13/2023



Separators – Photo #07490



Tank Battery – Photo #07491