

Inspection Photos

Loc: 322219

Operator: **SAN MARCO PETROLEUM INC**

Inspection Date: 11/08/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



Inspection Photos



Photo 2. Facing northeast toward the tank battery. Sign is posted at the tank battery.



Inspection Photos



Photo 3. Facing toward the front west side of the tanks. There is oil stained soil that needs to be cleaned up.



Inspection Photos



Photo 4. There is oil stained soils at the backside of the tanks.



Inspection Photos



Photo 5. There is oil stained soil at the pipe outlet.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:322219 | Date: 11/08/2023

Inspection Photos



Photo 6. Facing northeast toward the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:322219 | Date: 11/08/2023