

Inspection Photos

Loc: 322241

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 11/08/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:322241 | Date: 11/08/2023

Inspection Photos



Photo 2. Facing east by the separator. There is erosion along this area of the location that needs to be repaired and stabilized.



Inspection Photos



Photo 3. Facing southeast toward the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:322241 | Date: 11/08/2023

Inspection Photos



Photo 4. There is a one wire fence at the location which is not maintained and is not highly visible and could pose a collision hazard..

