

FORM
43

Rev
05/21

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

11/14/2023

Document Number:

403594622

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - OGCC Facility ID: 485209 Initial Form 19 or 27 Document number:
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6
County: WELD Field Name:
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Agent Name: Tanya Cude Title: Environmental Scientist
Phone Number: 352-318-4034 Email: Tanya.Cude@Absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 772245 Facility Name: Villani 228631 Facility Type: Domestic Well
Location: QtrQtr: SESE Sec: 25 Twp: 1N Range: 68W Meridian: 6
County Name: WELD Latitude: 40.018110 Longitude: -104.944020

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 114560 Document Name: NG4 File Name: 2023_10_12_Villani 228631 Isotech NG4 ECMC.xls
SampleType: Matrix:
Facility ID: 772245 Sample ID: 653644 Sample Name: VILLANI_228631 Sample Date: 10/12/2023
Collection Point: Dom Matrix: GAS Pre Post: Voluntary baseline sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 895491

Batch ID: 114553	Document Name: TB	File Name: 2023_10_12_Villani 228631 Trip Blank SGS ECMC.xls	
SampleType: _____		Matrix: _____	
Facility ID: 772245	Sample ID: 653633	Sample Name: VILLANI_228631	Sample Date: 10/12/2023
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary baseline sample	
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59342-1

Batch ID: 114560	Document Name: NG4	File Name: 2023_10_12_Villani 228631 Isotech NG4 ECMC.xls	
SampleType: _____		Matrix: _____	
Facility ID: 772245	Sample ID: 653645	Sample Name: VILLANI_228631	Sample Date: 10/12/2023
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample	
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 895491

Batch ID: 114554	Document Name: SGS	File Name: 2023_10_12_Villani 228631 SGS ECMC.xls	
SampleType: _____		Matrix: _____	
Facility ID: 772245	Sample ID: 653634	Sample Name: VILLANI_228631	Sample Date: 10/12/2023
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample	
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59320-1

Batch ID: 114556	Document Name: SIW	File Name: 2023_10_12_Villani 228631 Isotech SIW ECMC.xls	
SampleType: _____		Matrix: _____	
Facility ID: 772245	Sample ID: 653636	Sample Name: VILLANI_228631	Sample Date: 10/12/2023
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample	
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 893453

Batch ID: 114555	Document Name: dro	File Name: 2023_10_12_Villani 228631 SGS DRO ECMC.xls	
SampleType: _____		Matrix: _____	
Facility ID: 772245	Sample ID: 653635	Sample Name: VILLANI_228631	Sample Date: 10/12/2023
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample	
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59320-1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772245	403594696	2023_10_12_Villani 228631 Isotech SIW.pdf	Analytical Laboratory Report	PDF
772245	403594692	2023_10_12_Villani_228631_FS_ECMC.pdf	Field Data Report	PDF
772245	403594666	2023_10_12_Villani_228631_Spigot_Loc.jpg	Photographs	JPG
772245	403594662	2023_10_12_Villani 228631 SGS.pdf	Analytical Laboratory Report	PDF
772245	403594701	2023_10_12_Villani 228631 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772245	403594667	2023_10_12_Villani_228631_Wellhead.jpg	Photographs	JPG
772245	403594663	2023_10_12_Villani_228631_PrePostPurge.jpg	Photographs	JPG

772245	403594664	2023_10_12_Villani_228631_Spigot.jpg	Photographs	JPG
772245	403594668	2023_10_12_Villani_228631_Wellhead_Loc.jpg	Photographs	JPG
772245	403594658	2023_10_12_Villani 228631 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	11/14/2023
Total: 1 comment(s)		