



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

DANFORD 13-31 1

Location ID: **320168**

Tank Battery : North



Tank Battery : East



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200025**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

DANFORD 13-31 1

Location ID: **320168**

Tank Battery Sign



Separator : North



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200025**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

DANFORD 13-31 1

Location ID: **320168**

Well Head : North



Well Head : East



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200025**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

DANFORD 13-31 1

Location ID: **320168**

Well Head: South



Well Head: West



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200025**




COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

DANFORD 13-31 1

Location ID: **320168**

Well Head : GPS Screenshot



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200025**