



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

**ELAINE 41-18**

Location ID: **320103**

## Tank Battery : East



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

Inspection Number: **709200029**



## Well Head : North



## Well Head : East



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.



## Well Head: South



## Well Head: West



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.



## Well Head : GPS Screenshot



This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.