

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC WF CLOUGH FEDERAL 14-12-6S-94W Pad

Location ID: 322530



Photo # 6595 From entrance to location



Photo # 6596 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC WF CLOUGH FEDERAL 14-12-6S-94W Pad

Location ID: 322530



Photo # 6597 Location



Photo # 6598 Meter calibration info not conspicuously posted, no meter on location & no signage as to where meter is located.