

# Final Reclamation Inspection

November 2, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 333330

Inspection Document #: 697504951

Weld County, CO

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: SEELEY LAKE-66N66W 24SESW

Location ID: 333330



**Photo 1.** Photo taken from the associate off location tank battery, facing West. Photo illustrates all equipment has been removed. The area appears to be recently mowed and in process of establishing desirable vegetation.



**Photo 2.** Photo taken from the associate off location tank battery, facing Northwest. See comments under Photo 1.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 697504951



## Inspection Photos

Location Name: SEELEY LAKE-66N66W 24SESW

Location ID: 333330



**Photo 3.** Photo taken from the associate off location tank battery, facing North. Photo illustrates the access road was shared with agricultural activities and remains in use for ag purposes.



**Photo 4.** Photo taken from the well location, facing Southeast. Photo illustrates the crop field has been harvested. Staff will have to verify during the activities growing season.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 697504951



## Inspection Photos

Location Name: SEELEY LAKE-66N66W 24SESW

Location ID: 333330



**Photo 5.** Photo taken from the well location, facing Northeast.  
See comments under Photo 4.



**Photo 6.** Tank battery reference photo taken south of the tank battery, facing Southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 697504951