

# Final Reclamation Inspection

November 2, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 331001

Inspection Document #: 697504953

Weld County, CO

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MATT-64N67W 24NWSW  
Location ID: 331001



**Photo 1.** Photo taken from the off location tank battery, facing North. Photo illustrates the establishment of perennial vegetation, which has a higher percentage of perennial vegetation cover than the nearby reference areas.



**Photo 2.** Photo taken from the off location tank battery, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: MATT-64N67W 24NWSW  
Location ID: 331001



**Photo 3.** Photo taken from the off location tank battery, facing South. See comments under Photo 1.



**Photo 4.** Close up photo taken from the off location tank battery. Photo illustrates the establishment of perennial vegetation.



Inspection Photos  
Location Name: MATT-64N67W 24NWSW  
Location ID: 331001




**Photo 5.** Reference photo taken just north of the off location tank battery, facing North. Photo illustrates a dominance of annual vegetation that appears to have established after a recent stormwater run-on evident.



**Photo 6.** Another reference photo taken east of the off location tank battery, facing North. Photo illustrates a high density of cheatgrass mixed with sand dropseed.



Inspection Photos  
Location Name: MATT-64N67W 24NWSW  
Location ID: 331001



**Photo 7.** 2023 Operator supplied documentation of the wellhead. Subsidence was repaired in 2022 and is in process of establishing, as shown in the photos. The 2023 report noted continued subsidence even after the 2022 repairs and suggests additional repairs during sediment removal from a stormwater run-on event.

