

# Final Reclamation Inspection

November 2, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 323547

Inspection Document #: 697504955

Weld County, CO

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ELDRIDGE-66N66W 23SENE

Location ID: 323547



**Photo 1.** Photo taken from the eastern gated entrance of location, facing Southwest.



**Photo 2.** Photo taken from the eastern gated entrance of location, facing South. Photo illustrates salt grass establishment along the eastern location.



Inspection Photos

Location Name: ELDRIDGE-66N66W 23SENE

Location ID: 323547



**Photo 3.** Photo taken from the northern location, facing South. Photo illustrates the central location has been reseeded and establishment of germination was observed.



**Photo 4.** Photo taken from the western gated entrance of location, facing West. Photo illustrates tumbleweeds that are in need of weed management.



Inspection Photos

Location Name: ELDRIDGE-66N66W 23SENE

Location ID: 323547



**Photo 5.** Reference photo taken just east of the location, facing South. Photo illustrates a mixture of salt grass and annual weeds of Kochia.



**Photo 6.** Another reference photo taken from location, facing North. Photo illustrates housing development activity occurring.

