

Inspection Photos
Location Name: RANDALL 22-2
Location ID:320134



Photo #1 Tanks and weeds

Photo #2 weeds throughout location.

Inspection Photos
Location Name: RANDALL 22-2
Location ID:320134



Photo #3 Separator and weeds.

Photo #4 Produced water tank out side containment and not connected.

Inspection Photos
Location Name: RANDALL 22-2
Location ID:320134





Photo #5 meter house and weeds.

Photo #6 stained soil in separator cabinet.

Inspection Photos
Location Name: RANDALL 22-2
Location ID:320134




Photo #7 Separator with leak.



Photo #8 Stained soil under separator.

Inspection Photos
Location Name: RANDALL 22-2
Location ID:320134



Photo #9 Well head.