

Inspection Photos
UPRR 42 D2 Tank
Spill ID 481819/Remediation Project No 23780



Photo 1 – Battery location.



Photo 2 - Former tank location. Impacted soil visible.

Inspection Photos
UPRR 42 D2 Tank
Spill ID 481819/Remediation Project No 23780



Photo 3 – Former tank location. Impacted soil visible.



Photo 4 - Former tank location. Impacted soil visible.