

**Inspection Photos**  
**George Norden Consolidation**  
**Spill ID 479923/Remediation Project No 19716**



**Photo 1 – Open excavation.**



**Photo 2 - Open excavation.**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Inspection Photos**  
**George Norden Consolidation**  
**Spill ID 479923/Remediation Project No 19716**



**Photo 3 – Open excavation/weeds/fencing.**



**Photo 4 - Open excavation.**

**Inspection Photos**  
**George Norden Consolidation**  
**Spill ID 479923/Remediation Project No 19716**



**Photo 5 – Open excavation.**



**Photo 6 - Open excavation/weeds/fencing.**



**Inspection Photos**  
**George Norden Consolidation**  
**Spill ID 479923/Remediation Project No 19716**



**Photo 7 – Open excavation/weeds/fencing.**



**Photo 8 - Weeds/fencing.**



**Inspection Photos**  
**George Norden Consolidation**  
**Spill ID 479923/Remediation Project No 19716**



**Photo 9 – Open excavation.**



**Photo 10 - Open excavation.**