

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #1 Crude tank.



Photo #2 Stained soil around loadout bucket.

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #3 P/W vault.



Photo #4 Separator, Meter house & EDCs.

Inspection Photos
Location Name: UPRR 23 PAN AM D #2
Location ID: 319939



Photo #5 Trash on location.



Photo #6 Pump jack.