

Operator: CRESTONE PEAK RESOURCES

Location Name: OGREN H. UNIT-61N69W 11SESW

Loc ID: 321296

Inspection: 713300283



Exhibit A

CA: Produced water tank volume sign faded, unreadable. Install sign to comply with Rule 605.h.

CA Resolution: Operator has updated the signage on the Produced Water tank to display capacity to comply with Rule 605.h.