

Inspection Photos

Location Name: TEP Rocky Mountain LLC BURNS RMV 107-35 Pad

Location # 324113



Photo # 6691 From entrance to location



Photo # 6692 Location

Inspection Photos
Location Name: TEP Rocky Mountain LLC BURNS RMV 107-35 Pad
Location # 324113



Photo # 6693 Location



Photo # 6694 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BURNS RMV 107-35 Pad

Location # 324113



Photo # 6695 Location



Photo # 6696 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC BURNS RMV 107-35 Pad

Location # 324113




Photo # 6697 Unused equipment



Photo # 6698 Open ended load line