

Inspection Photos
Location Name: Shurview 13N-3HZ Pad
Location ID: 330461



Production facility



Wellheads

Inspection Photos
Location Name: Shurview 13N-3HZ Pad
Location ID: 330461



Energy & Carbon Management Commission
40.45238, -104.90001, 141°
11/16/2023 09:25:10

Trash



Energy & Carbon Management Commission
40.44814, -104.90147, 266°
11/16/2023 09:47:58

Trash

Inspection Photos
Location Name: Shurview 13N-3HZ Pad
Location ID: 330461



Lease road erosion



Lease road erosion

Inspection Photos
Location Name: Shurview 13N-3HZ Pad
Location ID: 330461



Lease road erosion



Lease road erosion

Inspection Photos
Location Name: Shurview 13N-3HZ Pad
Location ID: 330461



Lease road erosion