

Inspection Photos

Loc: 309105

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 11/14/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road which is stabilized with BMP's.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309105 | Date: 11/14/2023

Inspection Photos



Photo 2. Facing southwest further along the access road which is stabilized with BMP's.



Inspection Photos



Photo 3. Facing northwest toward the location.



Inspection Photos



Photo 4. Facing northwest at the location which consists of a uniform perennial vegetation cover.



Inspection Photos



Photo 5. Facing northeast at the location. A uniform perennial vegetation cover has re-established.



Inspection Photos



Photo 6. Facing south at the location. A uniform perennial vegetation cover has re-established.

