

# Inspection Photos

Loc: 308639

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 11/14/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east toward the location.



## Inspection Photos



**Photo 2.** Facing east along the fill slope which is stabilized with perennial vegetation..



## Inspection Photos



**Photo 3.** Facing toward the wellhead.



## Inspection Photos



**Photo 4.** This container has fallen over and needs to be installed with containment..

