

Inspection Photos

Loc: 308999

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 11/14/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Areas of erosion were repaired and culverts have been cleaned out..



Inspection Photos



Photo 2. Facing northwest toward the location.

