

Inspection Photos

Loc: 309427

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 11/14/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest at the location. The location has not been recontoured and a steep cut slope remains. Previous corrective action not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309427 | Date: 11/14/2023

Inspection Photos



Photo 2. There is a pit that remains along the base of the cut slope at the location.



Inspection Photos



Photo 3. The 3 steel casing previously observed at the center of the location have been removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309427 | Date: 11/14/2023

Inspection Photos



Photo 4. Facing southeast at the location. The location has not been recontoured and a steep cut slope remains. Previous corrective action not completed.



Inspection Photos



Photo 5. Facing east along the fill slope.



Inspection Photos



Photo 6. East side of the location facing south.

