

Inspection Photos
Location Name: UPRR 23 PAN AM B #2
Location ID: 319928



Photo #1 Crude tank & P/W vault.



Photo #2 Weeds in the berm.

Inspection Photos
Location Name: UPRR 23 PAN AM B #2
Location ID: 319928



Photo #3 Meter & Separator.



Photo #4 Well head