

Operator: CIVITAS NORTH LLC

Location Name: BASHOR-69N60W 18SWNW

Loc ID: 323023

Inspection: 708200677



Exhibit AExhibit A

CA: Debris/trash observed around the tank battery facility. Refer to attached inspection photos. Comply with Rule 606. The location will remain out of compliance until the corrective action has been resolved.

CA Resolution: Operator has addressed the identified weed debris/trash on location and it has been appropriately cleared.