

Inspection Photos

Simcoe Beaver Creek 2

API 067-08923



**Photo #1. View of corrective action identified in FIR
Doc.#712700754.**



Photo #2. View of completed corrective action.

Inspection Photos
Simcoe Beaver Creek 2
API 067-08923



Photo #3. View of corrective action identified in FIR Doc.#712700754.



Photo #4. View of completed corrective action.

Inspection Photos
Simcoe Beaver Creek 2
API 067-08923



Photo #5. View of installed solar array, north side of location.



Photo #6. View of installed solar array, east side of location.