

Final Reclamation Inspection

November 1st, 2023

Operator: Logos Operating - 10679

Location ID: 325222

Inspection Document #: 714000105

La Plata County, CO

Township: SWNW 15 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ignacio 33-8 14
Location ID: 325222

11/1/23
+37.107696,-107.709482
228° SW



Photo 1. View of the project area from the access road entrance facing center. Note: northeast portion of the disturbance remains unreclaimed with gravel and farm equipment stored on location.

Inspection Photos
Location Name: Ignacio 33-8 14
Location ID: 325222

11/1/23
+37.107316,-107.709877
358° N



Photo 2. View of the southern portion of the project area facing north.

Inspection Photos
Location Name: Ignacio 33-8 14
Location ID: 325222



Photo 3. View of the access road that remains unreclaimed on location.

Inspection Photos
Location Name: Ignacio 33-8 14
Location ID: 325222

11/1/23
+37.107334,-107.709359
118° SE



Photo 4. Reference area comprised of smooth brome, crested wheatgrass and sagebrush.