

Final Reclamation Inspection

November 1st, 2023

Operator: Arkoma Operations LLC - 10766

Location ID: 333602

Inspection Document #: 714000107

La Plata County, CO

Township: SESE 8 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 1. View of the project area taken from the entrance facing center.
Note: project area is dominated by undesirable plant species including cheatgrass and russian thistle.

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



11/1/23
+37.113985,-107.735525
20° N

Photo 2. View of the project area taken from the southern edge facing north. Note: large bare patch of soil observed in the center of the project area.

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 3. View of erosion/stormwater BMPs at the center of the project area that are not functioning properly.

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 4. View of the access road/access point that remains unreclaimed with gravel in the northeast portion of the project area.

Inspection Photos
Location Name: Olson Smith Unit 1
Location ID: 333602



Photo 5. Reference area comprised of sagebrush and poa secunda.